

# Work Order ID 51763

September 03, 2009 8:58:19 AM



Page 1

Item ID: D2856-400-720

Accept



Setup Start



Revision ID: A

Stop



Item Name: Abrasion Strip

Start Date: 09/02/09 Start Qty: 4.00



Cust Item ID:

Required Date: 09/16/09 Req'd Qty: 4.00



Customer:

Reference: Return 2009 / RA109088

Approvals: Process Plan: \_\_\_\_\_ Date: \_\_\_\_\_ Tooling: \_\_\_\_\_ Date: \_\_\_\_\_

Run Start



QC: \_\_\_\_\_ Date: \_\_\_\_\_ SPC (Y/N): \_\_\_\_\_ Date: \_\_\_\_\_

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D2856	Rev A

100 QC5- Inspect part completeness to step on W/O 0.00



QC Memo 0.00

Quality Control Original B46543. Still in bag.

4/ 09-09-02

110 Identify as per dwg & Stock Location: Y03 0.00



Packaging Memo 0.00

Packaging Return to stock with the new batch #.  
Location: \_\_\_\_\_

Run "Return 2009". Have LC make adjustment.

120 QC21- Final Inspection - Work Order Release 0.00



QC Memo 0.00

Quality Control

(4) 09/09/08  
MF 09-09-08